

[Instruction Set](#) > [CIP Axis Attributes](#) > General Permanent Magnet Motor Attributes

General Permanent Magnet Motor Attributes

These are the motor configuration attributes that apply to Permanent Magnet motor types in general.

PM Motor Resistance

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
Required	Set/SSV*	REAL	0 DB	0		Ohms

** Indicates the attribute cannot be set while the drive power structure is enabled (Power Structure Enable bit in CIP Axis Status is true).*

The PM Motor Resistance attribute is a floating point value that specifies the phase-to-phase, resistance of a permanent magnet motor.

PM Motor Inductance

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
Required (SPM Only)	Set/SSV*	REAL	0 DB	0		Henries

** Indicates the attribute cannot be set while the drive power structure is enabled (Power Structure Enable bit in CIP Axis Status is true).*

The PM Motor Inductance attribute is a floating point value that specifies the phase-to-phase, inductance of a permanent magnet motor.

PM Motor Flux Saturation

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
Optional (SPM Only)	Set	REAL [8]	[100, 100, 100, 100, 100, 100, 100, 100, 100] DB	0	100	% Nominal Inductance

The PM Motor Flux Saturation attribute is an array of floating point values that specify the amount of flux saturation in the motor as a function of current. The units for the nominal inductance values are percent, such that a value of 100% means no saturation, and 90% means the inductance is 90% of its value at zero current.

The first array entry specifies the flux saturation value at 12.5% of the Peak Current Rating; the second entry specifies the value at 25%, and so on up to the last entry, which specifies the value at 100% of the Peak Current Rating. (At zero current, the motor is assumed to have no saturation, for example, an implied value of 100%.)

PM Motor Lq Inductance

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
-------	--------	-----------	---------	-----	-----	---------------------

Search



- ▷ [Quick Start Steps](#)
- ▷ [Logix Designer](#)
- ▷ [Module Information](#)
- ◀ [Instruction Set](#)

[Logix 5000 Controllers Instruction and Application Considerations](#)

[Logix Designer Application Instruction Set](#)

[Interpret the Attribute Tables Array Concepts](#)
- ◀ [CIP Axis Attributes](#)

[AXIS_CIP_DRIVE Diagrams](#)

[AXIS_CIP_DRIVE Structure](#)

▷ [Accessing Attributes](#)

[AC Line Condition Attributes](#)

[Acceleration Control Attributes](#)

[Acceleration Control Configuration Attributes](#)

[Additional Error Code Information](#)

▷ [APR Fault Attributes](#)

[Auto-Tune Configuration Attributes](#)

▷ [Axis Exception Action Configuration Attributes](#)

[Axis Info Attributes](#)

[Axis Safety Status Attributes](#)

[Axis Statistical Attributes](#)

[CIP Axis Status Attributes](#)

[CIP Error Codes](#)

[CIP Motion Axis Control Modes](#)

▷ [Command Reference](#)

[Generation Attributes](#)

[Configuration Fault Attributes](#)

[Control Mode Attributes](#)

[Converter AC Line Configuration Attributes](#)

[Converter AC Line Monitoring Attributes](#)

[Converter AC Line Source Configuration Attributes](#)

[Converter Bus Voltage Control Configuration Attributes](#)

[Converter Bus Voltage Control Signal Attributes](#)

[Converter Control Mode Attributes](#)

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
Required (IPM Only)	Set/SSV*	REAL	0 DB	0		Henries

* Indicates the attribute cannot be set while the drive power structure is enabled (Power Structure Enable bit in CIP Axis Status is true).

The PM Motor Lq Inductance attribute is a floating point value that specifies the phase-to-neutral, q-axis, inductance of an interior permanent magnet motor.

PM Motor Ld Inductance

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
Required (IPM Only)	Set/SSV*	REAL	0 DB	0		Henries

* Indicates the attribute cannot be set while the drive power structure is enabled (Power Structure Enable bit in CIP Axis Status is true).

The PM Motor Ld Inductance attribute is a floating point value that specifies the phase-to-neutral, d-axis, inductance of an interior permanent magnet motor.

PM Motor Lq Flux Saturation

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
Optional (IPM Only)	Set	REAL [8]	[100, 100, 100, 100, 100, 100, 100, 100] DB	0	100	% Nominal Inductance

The PM Motor Lq Flux Saturation attribute is an array of floating point values that specify the amount of q-axis flux saturation in the motor as a function of current. The units for q-axis flux saturation values are percent of Nominal Inductance, such that a value of 100% means no saturation, and 90% means the inductance is 90% of its value at zero current given by the PM Motor Lq Inductance attribute.

The first array entry specifies the flux saturation value at 25% of the Continuous Current Rating; the second entry specifies the value at 50%, and so on up to the last entry, which specifies the value at 200% of the Peak Current Rating. (At zero current, the motor is assumed to have no saturation, for example, an implied value of 100%.)

PM Motor Ld Flux Saturation

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
Optional (IPM Only)	Set	REAL	100 DB	0	100	% Nominal Inductance

The PM Motor Lq Flux Saturation attribute is an array of floating point values that specify the amount of d-axis flux saturation in the motor at rated current. The units for d-axis flux saturation values are percent of Nominal Inductance, such that a value of 100% means no saturation, and 90% means the inductance is 90% of its value at zero current given by the PM Motor Ld Inductance attribute.

[Attributes](#)

[Converter Current Control Configuration Attributes](#)

[Converter Current Control Signal Attributes](#)

[Converter Current Reference Configuration Attributes](#)

[Converter Current Reference Signal Attributes](#)

[Converter Output Attributes](#)

[Converter Reactive Power Control Attributes](#)

[Converter Types](#)

[Current Control Signal Attributes](#)

[Current Control Configuration Attributes](#)

[Cyclic Read and Cyclic Write](#)

[DC Bus Condition Attributes](#)

[Device Function Codes](#)

[Device Commissioning Attributes](#)

[Drive General Purpose I/O Attributes](#)

[Drive Output Attributes](#)

[Drive Parameters](#)

[Event Capture Attributes](#)

[Exception Factory Limit Info Attributes](#)

[Exception User Limit Configuration Attributes](#)

[Exception, Fault and Alarm Attributes](#)

[Exceptions](#)

[Fault and Alarm Behavior](#)

[Feedback Interface Types](#)

[Feedback Configuration Attributes](#)

[Frequency Control Configuration Attributes](#)
[Frequency Control Signal Attribute](#)

[General Feedback Info Attributes](#)

[General Feedback Signal Attributes](#)

[General Linear Motor Attributes](#)

[General Motor Attributes](#)

[General Permanent Magnet Motor Attributes](#)

[General Rotary Motor](#)

The PM Motor Ld Flux Saturation value specifies the d-axis saturation at 100% of the Continuous Current Rating.

PM Motor Extended Speed Permissive

Usage	Access	Data Type	Default	Min	Max	Semantics of Values
Optional - PVT (PM Only)	Set/SSV	USINT	0	0	1	Enumeration: 0 = False 1 = True

The PM Motor Extended Speed Permissive attribute value determines whether the speed of a PM motor is allowed to exceed the Bus Overvoltage Speed. Setting this value to True removes velocity limit protection against Bus Overvoltage conditions associated with Rotary and Linear PM motors. In this case it is critical that Bus Overvoltage protection be provided through a resistive brake module or DC bus regulation device to avoid drive damage.

Specifically, the PM Motor Extended Speed Permissive determines if the Bus Overvoltage Speed is applied to the velocity limiter function. The Bus Overvoltage Speed is only applied to the velocity limiter if the PM Motor Extended Speed Permissive is False.

The PM Motor Extended Speed Permissive value also determines the values of the Motor Overspeed Factory Limit and Motor Overspeed User Limit that provide overspeed protection. If the PM Motor Extended Speed Permissive is False, the Motor Overspeed Limits will be based on the Bus Overvoltage Speed. If the PM Motor Extended Speed Permissive is True, the Motor Overspeed Limits will be based on the Max Extended Speed value.

See also

[General Motor Attributes](#)

[Induction Motor Attributes](#)

[Linear PM Motor Attributes](#)

[Motor Attributes Model](#)

[Rotary PM Motor Attributes](#)

[Attributes](#)

[Guard Safety Attributes](#)

[Guard Safety Status
Attributes](#)

[Hookup Test Configuration
Attributes](#)

[Hookup Test Result
Attributes](#)

[Identify Motion Axis
Attributes Based on Device
Function Codes](#)

[Induction Motor Attributes](#)

[Inertia Test Configuration
Attributes](#)

[Inertia Test Result
Attributes](#)

[Initialization Faults
Attributes](#)

[Interior Permanent Magnet
Motor Attributes](#)

[Linear PM Motor Attributes](#)

[Load Transmission and
Actuator Attributes](#)

[Local Mode Configuration
Attribute](#)

[Module/Node Fault and
Alarm Attributes](#)

▷ [Motion Control Axis
Behavior Model](#)

[Motion Control
Configuration Attributes](#)

[Motion Control Interface
Attributes](#)

[Motion Control Methods](#)

[Motion Control Modes](#)

[Motion Control Signal
Attributes](#)

[Motion Control Status
Attributes](#)

[Motion Database Storage
Attributes](#)

[Motion Dynamic
Configuration Attributes](#)

[Motion Fault and Alarm
Exceptions](#)

[Motion Homing
Configuration Attributes](#)

[Motion Instruction
Compatibility](#)

[Motion Planner
Configuration Attributes](#)

[Motion Planner Output
Attributes](#)

▷ [Motion Scaling Attributes
Motor Attributes](#)

[Motor Attributes Model](#)

[Motor Attributes Model](#)

[Motor Test Result Attributes](#)

[No Control Mode](#)

[Position Control Mode](#)

[Position Loop Signal Attributes](#)

[Position Loop Configuration Attributes](#)

[Power and Thermal Management Configuration Attributes](#)

[Power and Thermal Management Status Attributes](#)

[Replicated Attributes](#)

[Required vs. Optional Axis Attributes](#)

[Reset an APR Fault](#)

[Rockwell Automation Specific CIP Axis Alarm Names](#)

[Rockwell Automation Specific Exceptions](#)

[Rockwell Automation Specific CIP Axis Fault Names](#)

[Rockwell Automation Specific Initialization Faults](#)

[Rockwell Automation Specific Start Inhibits](#)

[Rotary PM Motor Attributes Standard CIP Axis Fault and Alarm Names](#)

[Standard Exceptions](#)

[Rotary PM Motor Attributes Standard Initialization Faults](#)

[Standard Start Inhibits](#)

[Start Inhibits Attributes](#)

[State Behavior](#)

▷ [Stopping and Braking Attributes](#)

[Torque Control Mode](#)

[Torque/Force Control Configuration Attributes](#)

[Torque/Force Control Signal Attributes](#)

[Velocity Control Mode](#)

[Velocity Loop Configuration Attributes](#)

[Velocity Loop Signal Attributes](#)

▷ [Module Configuration Attributes](#)

[Bit Addressing](#)

[Common Attributes](#)

[Data Conversions](#)

[Elementary data types](#)

[LINT data types](#)

[Floating Point Values](#)

[Immediate values](#)

[Index Through Arrays](#)

[Math Status Flags](#)

[Motion Error Codes \(.ERR\)](#)

[Structures](#)

- ▷ [Equipment Sequence instructions](#)
- ▷ [Equipment Phase Instructions](#)
- ▷ [Alarm Instructions](#)
- ▷ [Advanced Math Instructions](#)
- ▷ [Array_\(File\)/Misc Instructions](#)
- ▷ [Array_\(File\)/Shift Instructions](#)
- ▷ [ASCII Conversion Instructions](#)
- ▷ [ASCII Serial Port Instructions](#)
- ▷ [ASCII String Instructions](#)
- ▷ [Bit Instructions](#)
- ▷ [Compare Instructions](#)
- ▷ [Debug Instructions](#)
- ▷ [Drives Instructions](#)
- ▷ [Drive Safety Instructions](#)
- ▷ [For/Break Instructions](#)
- ▷ [Filter Instructions](#)
- ▷ [Function Block Attributes](#)
- ▷ [Structured Text Attributes](#)
- ▷ [Compute/Math Instructions](#)
- ▷ [Move/Logical Instructions](#)
- ▷ [Input/Output Instructions](#)
- ▷ [License Instructions](#)
- ▷ [Math Conversion Instructions](#)
- ▷ [Metal Form Instructions](#)
- ▷ [Motion Configuration Instructions](#)
- ▷ [Motion Event Instructions](#)
- ▷ [Motion Group Instructions](#)
- ▷ [Motion Move Instructions](#)
- ▷ [Motion State Instructions](#)
- ▷ [Multi-Axis Coordinated Motion Instructions](#)
- ▷ [Logical and Move Instructions](#)
- ▷ [Program Control Instructions](#)
- ▷ [Sequencer Instructions](#)
- ▷ [Special Instructions](#)
- ▷ [Timer and Counter Instructions](#)
- ▷ [Trigonometric Instructions](#)
- ▷ [Process Control Instructions](#)

- ▷ [Select/Limit Instructions](#)
- ▷ [Sequential Function Chart \(SFC\) Instructions](#)
- ▷ [Statistical Instructions](#)
- ▷ [Safety Instructions](#)
- ▷ [Studio 5000 Logix Designer Glossary](#)

Copyright © 2019 Rockwell Automation Technologies, Inc. All Rights Reserved.

[How are we doing?](#)